

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/22/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 045176	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 10/05/2005
NAME OF PROVIDER OR SUPPLIER BEVERLY HEALTHCARE MONTICELLO			STREET ADDRESS, CITY, STATE, ZIP CODE 1194 N CHESTER ST MONTICELLO, AR 71655	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	<p>INITIAL COMMENTS</p> <p>§483.70 Physical environment.</p> <p>The facility must be designed, constructed, equipped, and maintained to protect the health and safety of residents, personnel and the public.</p> <p>(a) Life safety from fire.</p> <p>Except as provided in paragraph (a)(1) or (a)(3) of this section, the facility must meet the applicable provisions of the 1985 edition of the Life Safety Code of the National Fire Protection Association (which is incorporated by reference). Incorporation of the 1985 edition of the National Fire Protection Association's Life Safety Code (published February 7, 1985; ANSI/NFPA) was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR Part 51 that govern the use of incorporations by reference. The Code is available for inspection at the Office of the Federal Information Center, Room 8301, 1110 L Street N.W., Washington, D.C. Copies may be obtained from the National Fire Protection Association, Batterymarch Park, Quincy, Mass. 02200. If any changes in this code are also to be incorporated by reference, a notice to that effect will be published in the Federal Register.</p> <p>(1) A facility is considered to be in compliance with this requirement as long as the facility--</p> <p>(i) On November 26, 1982, complied with or without waivers, with the requirements of the 1967 or 1973 editions of the Life Safety Code and continues to remain in compliance with those</p>	K 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/22/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 045176	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 10/05/2005
NAME OF PROVIDER OR SUPPLIER BEVERLY HEALTHCARE MONTICELLO			STREET ADDRESS, CITY, STATE, ZIP CODE 1194 N CHESTER ST MONTICELLO, AR 71655		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	Continued From page 1 editions of the Code; or (ii) On May 9, 1988, complied, with or without waivers, with the 1981 edition of the Life Safety Code and continues to remain in compliance with that edition of the Code. (2) After consideration of State survey agency findings, HCFA may waive specific provisions of the Life Safety Code which, if rigidly applied, would result in unreasonable hardship upon the facility, but only if the waiver does not adversely affect the health and safety of residents or personnel. (3) The provisions of the Life Safety Code do not apply in a State where HCFA finds, in accordance with applicable provisions of sections 1819(d)(2)(B)(ii) and 1919(d)(2)(B)(ii) of the Act, that a fire and safety code imposed by State law adequately protects patients, residents and personnel in long term care facilities. Based on evidence at K067 this standard was not met.	K 000			
K 067 SS=C	NFPA 101 LIFE SAFETY CODE STANDARD Heating, ventilating, and air conditioning comply with the provisions of section 9.2 and are installed in accordance with the manufacturer's specifications. 19.5.2.1, 9.2, NFPA 90A, 19.5.2.2 This STANDARD is not met as evidenced by:	K 067			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/22/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 045176	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 10/05/2005
NAME OF PROVIDER OR SUPPLIER BEVERLY HEALTHCARE MONTICELLO			STREET ADDRESS, CITY, STATE, ZIP CODE 1194 N CHESTER ST MONTICELLO, AR 71655		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 067	Continued From page 2 Based on observation, the facility failed to ensure the corridors were not used as return air plenums. This failed practice had the potential to affect all 91 residents, as documented on the Resident Census and Conditions of Residents form dated 10/03/05. The findings are: On 10/5/05, the corridors were used as return air plenums.	K 067			